






ondabox.cor 30 design








gondabox.co 3D design



To secure the model using the front fork attachment.

Start the attachment assembly by installing the M3 screw into the oscillate piece and the fork support nut onto the screw.




Complete assembling the front fork attachment by installing the base using the fixing screw.











In these instructions we show two different configurations with which to align your model. The CubiJIG modular design allows for numerous configurations to suit the specific needs of each model.


The threaded rods supplied fit the length and width of most models on the market. If you need a greater length or width, you can replace the rods supplied with an M5 threaded rod of the length you need.

Complete your CubiJIG with the range of accessories available.





gondabox.cor 3D design







gondabox.cor 3D design